



Report

US \$44.99

2021 Ford Bronco First Edition Advanced

236 mi | VIN: 1FMEE5EP1MLA40176

4 Door Wagon/Sport Utility | 2.7L V6 F DOHC 24V | Gasoline | All wheel drive



NO ACCIDENTS REPORTED

No Accidents or Damage Reported to CARFAX

3 Service History Records

At Least 1 Open Recall

CARFAX 1-Owner Vehicle

Personal Vehicle

Last Owned in Louisiana

This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 6/7/26 at 10:56:19 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

Additional History Not all accidents / issues are reported to CARFAX	Owner 1
Total Loss No total loss reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Structural Damage No structural damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Airbag Deployment No airbag deployment reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Odometer Check No indication of an odometer rollback.	<input checked="" type="checkbox"/> No Issues Indicated
Accident / Damage No accidents or damage reported to CARFAX.	<input checked="" type="checkbox"/> No Issues Reported
Manufacturer Recall At least 1 manufacturer recall requires service. Locate an authorized Ford or Lincoln Mercury dealer or call 866-436-7332 to obtain more information about this recall.	Recall Reported
Basic Warranty Original warranty estimated to have expired.	Warranty Expired

Title History CARFAX guarantees the information in this section	Owner 1
Damage Brands Salvage Junk Rebuilt Fire Flood Hail Lemon	<input checked="" type="checkbox"/> Guaranteed No Problem
Odometer Brands Not Actual Mileage Exceeds Mechanical Limits	<input checked="" type="checkbox"/> Guaranteed No Problem



GUARANTEED - None of these title problems were reported by a U.S. state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, you may qualify.
[View Terms](#) | [View Certificate](#)

CARFAX Ownership History		Owner 1
The number of owners is estimated		
Year purchased		2021
Type of owner		Personal
Estimated length of ownership		4 yrs. 11 mo.
Owned in the following states/provinces		Louisiana
Estimated miles driven per year		---
Last reported odometer reading		236



CARFAX Detailed History				
Owner 1 Purchased: 2021		Personal Vehicle		
Date	Mileage	Source		Comments
06/29/2021		Ford Motor Company		Vehicle manufactured and shipped to original dealer Original Window Sticker
07/07/2021	7	Matt Bowers Ford Metairie, LA 888-709-0488 mbfordmetairie.com/ ★ 4.5 / 5.0 687 Verified Reviews ❤️ 6,600 Customer Favorites		Vehicle serviced - Pre-delivery inspection completed
07/07/2021		Louisiana Motor Vehicle Dept.		Vehicle purchase reported - Titled or registered as personal vehicle
07/28/2021		Louisiana Motor Vehicle Dept. Metairie, LA		Title issued or updated - First owner reported - Vehicle color noted as Gray
09/17/2021	231	Matt Bowers Ford Metairie, LA 888-709-0488 mbfordmetairie.com/ ★ 4.5 / 5.0 687 Verified Reviews ❤️ 6,600 Customer Favorites		Vehicle serviced - Maintenance inspection completed
11/28/2021	236	Matt Bowers Ford Metairie, LA 888-709-0488 mbfordmetairie.com/ ★ 4.5 / 5.0 687 Verified Reviews ❤️ 6,600 Customer Favorites		Vehicle serviced - Maintenance inspection completed
06/13/2022		Ford Motor Company		Manufacturer Safety recall issued - NHTSA #22V411 - Recall #22S44 REAR DOOR CHILD SAFETY LOCK INSPECTION

- Status: Remedy Available

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

[Learn more about this recall](#)

Description: IN SOME OF THE AFFECTED VEHICLES, THE REAR DOOR MAY BE OPENED FROM THE INSIDE OF THE VEHICLE, DESPITE THE INDICATION OF THE CHILD SAFETY LOCK IN THE ON POSITION.

IF THE CHILD SAFETY LOCK IS NOT FUNCTIONING CORRECTLY, A REAR DOOR MAY BE OPENED FROM THE INSIDE, INCREASING THE RISK OF INJURY TO AN UNRESTRAINED SECOND-ROW OCCUPANT.

Remedy: FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO INSPECT AND REPLACE THE REAR DOOR LATCH IF NEEDED FREE OF CHARGE PARTS AND LABOR.

05/25/2023

Louisiana
Motor Vehicle Dept.
Metairie, LA**Registration issued or renewed**

- Vehicle color noted as Gray

07/05/2023

Ford Motor Company

Manufacturer Safety recall issued

- NHTSA #23V358
- Recall #23C16 SEAT BELT LATCH PLATE ACCESS
- Status: Remedy Available

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

[Learn more about this recall](#)

Description: ON YOUR VEHICLE, IF THE FIRST-ROW SEATS IS IN A CERTAIN POSITION, THE DRIVER AND OR PASSENGER MAY HAVE DIFFICULTY ACCESSING THE SEAT BELT LATCH AND THEREFORE MAY NOT PUT IT ON.

FIRST ROW OCCUPANTS MAY EXPERIENCE DISSATISFACTION OR BE DISCOURAGED IF THEY ARE UNABLE TO EASILY ACCESS THE SEAT BELT LATCH PLATE IN ITS STOWED POSITION. DRIVING WITHOUT THE USE OF A SEATBELT INCREASES THE RISK OF INJURY IN A CRASH.

Remedy: PARTS ARE NOW AVAILABLE TO REPAIR YOUR VEHICLE. FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO INSTALL THE SEATBELT SLIDING CLIP ON THE FRONT DRIVER AND PASSENGER SEATBELTS AND PROVIDE A COPY OF THE OWNERS MANUAL ADDENDUM FREE OF CHARGE PARTS AND LABOR.

10/04/2023

Ford Motor Company

Manufacturer Safety recall issued

- NHTSA #23V598
- Recall #23S48 REPLACE REAR VIEW CAMERA
- Status: Remedy Available

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

[Learn more about this recall](#)

Description: YOU MAY INTERMITTENTLY EXPERIENCE A REAR CAMERA BLUE OR BLACK IMAGE ON THE SYNC SCREEN WHEN THE VEHICLE IS PLACED IN REVERSE. ONCE DISPLAYED, THE REAR CAMERA BLUE OR BLACK IMAGE MAY PERSIST FOR THE REMAINDER OF THE IGNITION ON CYCLE. ONCE PRESENT, THE ISSUE IS LIKELY TO REOCCUR ON SUBSEQUENT KEY CYCLES

THE LOSS OF THE REAR CAMERA IMAGE, WHILE IN REVERSE, INCREASES THE RISK OF A CRASH.

Remedy: PARTS ARE NOW AVAILABLE TO REPAIR YOUR VEHICLE. FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO REPLACE THE REAR VIEW CAMERA FREE OF CHARGE PARTS AND LABOR.

09/30/2024

Ford Motor Company

Manufacturer Safety recall issued

- NHTSA #24V635
- Recall #24S55 ENGINE VALVE INSPECTION TEST
- Status: Remedy Available

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

[Learn more about this recall](#)

Description: ON YOUR VEHICLE, IT MAY BE POSSIBLE THAT AN ENGINE VALVE MAY CRACK AND LEAD TO AN ENGINE FAILURE. AN ENGINE FAILURE CAN LEAD TO A LOSS OF MOTIVE POWER WHICH CAN INCREASE THE RISK OF A CRASH.

Remedy: PARTS ARE NOW AVAILABLE TO REPAIR YOUR VEHICLE. FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO INSPECT THE VEHICLE WITH AN ENGINE VALVE INSPECTION TEST FREE OF CHARGE.

01/21/2025

Ford Motor Company

Manufacturer Safety recall issued

- NHTSA #25V025
- Recall #25S01 REAR SHOCK ABSORBER EXTERNAL RESERVOIR CORROSION
- Status: Remedy Available

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

[Learn more about this recall](#)

Description: ON YOUR VEHICLE, IT MAY BE POSSIBLE THAT THE REAR SHOCK ABSORBERS MAY EXPERIENCE CORROSION BETWEEN THE EXTERNAL RESERVOIR, MOUNTING FLANGE AND THE DAMPER BODY, RESULTING IN POSSIBLE SEPARATION OF THE EXTERNAL RESERVOIR. CUSTOMERS MAY EXPERIENCE A BOUNCY RIDE, NOISE, OR LEAKING FLUID NEAR THE REAR WHEELS PRIOR TO THE DETACHMENT OF AN EXTERNAL RESERVOIR.

IF A REAR SHOCK ABSORBER EXTERNAL RESERVOIR SEPARATES FROM THE VEHICLE, IT CAN CREATE A POTENTIAL ROAD HAZARD FOR OTHER ROAD USERS, INCREASING THE RISK OF A CRASH.

Remedy: PARTS ARE NOW AVAILABLE TO REPAIR YOUR VEHICLE. FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO INSPECT THE REAR SHOCKS FOR LEAKING OR MISSING REAR SHOCK ABSORBER RESERVOIRS AND REPAIR OR REPLACE FREE OF CHARGE.

05/24/2025

Louisiana
Motor Vehicle Dept.
Metairie, LA

Registration issued or renewed
- Vehicle color noted as Gray

10/29/2025

Ford Motor Company

Manufacturer Safety recall issued
- NHTSA #25V721
- Recall #25SB5 FRONT SEAT HEIGHT-ADJUST PIVOT BOLTS AND LINKS INSPECTION
- Status: Remedy Available

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

[Learn more about this recall](#)

Description: ON YOUR VEHICLE, IT MAY BE POSSIBLE FOR ONE OF THE SEAT FRAME HEIGHT-ADJUST PIVOT BOLTS TO BECOME LOOSE AND EVENTUALLY DISLodge ON ONE OR BOTH FRONT SEATS.

IF THE SEAT FRAME HEIGHT-ADJUST PIVOT BOLT COMES OUT OF THE PIVOT JOINT, THIS CAN INCREASE THE RISK OF INJURY IN A CRASH.

Remedy: PARTS ARE NOW AVAILABLE TO REPAIR YOUR VEHICLE. FORD MOTOR COMPANY HAS AUTHORIZED YOUR DEALER TO INSPECT BOTH FRONT SEAT FRAME HEIGHT-ADJUST PIVOT BOLTS FOR PROPER TORQUE. IF FOUND TO BE LOOSE, YOUR DEALER WILL REPLACE THE SEAT FRAME HEIGHT-ADJUST PIVOT BOLTS AND LINKS FREE OF CHARGE.

03/05/2026

Ford Motor Company

Manufacturer Safety recall issued
- NHTSA #26V124
- Recall #26S09 INFOTAINMENT SCREEN BLANK
- Status: Remedy Available

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

[Learn more about this recall](#)

Description: ON YOUR VEHICLE, IT MAY BE POSSIBLE TO EXPERIENCE AN UNEXPECTED BLANK INFOTAINMENT SCREEN DUE TO THE APIM ACCESSORY PROTOCOL INTERFACE MODULE TEMPORARILY SHUTTING DOWN WHEN DETECTING HIGH TEMPERATURES. WHEN THE APIM SHUTDOWN OCCURS, YOUR VEHICLE CAN NO LONGER DISPLAY THE REARVIEW CAMERA IMAGE WHILE IN REVERSE.

A REARVIEW CAMERA IMAGE THAT DOES NOT DISPLAY WHILE IN REVERSE GEAR CAN REDUCE YOUR VIEW OF WHAT IS BEHIND THE VEHICLE, INCREASING THE RISK OF A CRASH.

Remedy: SOFTWARE IS AVAILABLE TO REPAIR YOUR VEHICLE. YOUR VEHICLE IS CAPABLE OF FORD SOFTWARE UPDATES AND CAN BE UPDATED AUTOMATICALLY, OR YOU CAN VISIT YOUR DEALER FOR THE SOFTWARE INSTALLATION. WHEN AUTOMATIC UPDATES ARE TURNED ON STANDARD FROM THE FACTORY, THE SOFTWARE WILL BE DOWNLOADED TO YOUR VEHICLE OVER A PRIVATE WI-FI NETWORK OR THROUGH YOUR VEHICLES MODEM THROUGH THE CELLULAR NETWORK. THE SOFTWARE INSTALLATION WILL HAPPEN AFTER THE DOWNLOAD. NOTE REFER TO FORD.COMSUPPORT FOR FURTHER INFORMATION ON YOUR FORD SOFTWARE UPDATES SYSTEM. SHOULD THE SOFTWARE FAIL TO LOAD OR INSTALL PROPERLY, FORD HAS AUTHORIZED YOUR DEALER TO INSTALL 26S09 SOFTWARE FREE OF CHARGE UNDER THE TERMS OF THIS PROGRAM.

05/15/2026

Ford Motor Company

Manufacturer Safety recall issued
- NHTSA #26V299
- Recall #26S32 ROOF PANEL DELAMINATION

- Status: Remedy Not Yet Available

Locate an authorized Ford or Lincoln dealer or call 866-436-7332 to obtain more information

[Learn more about this recall](#)

Description: THE HARD TOP ROOF ON YOUR VEHICLE MAY EXHIBIT DELAMINATION OR CRACKING ON THE ROOF PANEL EXTERIOR DUE TO ENVIRONMENTAL EXPOSURE. IN SEVERE CASES, DELAMINATION CAN PROGRESS TO DETACHMENT OF SECTIONS OF THE OUTER ROOF LAYER WHILE DRIVING.

DETACHMENT OF A SECTION OF THE HARD TOP OUTER LAYER WHILE DRIVING CAN CREATE A ROAD HAZARD FOR OTHER ROAD USERS, INCREASING THE RISK OF A CRASH.

Remedy: A REMEDY IS NOT YET AVAILABLE. FORD MOTOR COMPANY IS WORKING TO PROVIDE PARTS FOR THIS REPAIR. WHEN THE REMEDY BECOMES AVAILABLE, FORD MOTOR COMPANY WILL NOTIFY YOU VIA MAIL TO SCHEDULE A SERVICE APPOINTMENT WITH YOUR DEALER FOR REPAIRS TO BE COMPLETED FREE OF CHARGE. THE REMEDY IS ANTICIPATED TO BE AVAILABLE IN THE 4TH QUARTER OF 2026.

06/07/2026

CARFAX Car Care

Manufacturer Recommended Maintenance Schedules

Get this vehicle's maintenance schedule, service history and recall alerts at carfax.com/service.

Have Questions? Please visit our Help Center at www.carfax.com.



Glossary

First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Ford or Lincoln Mercury Recall

The Ford Motor Company provides CARFAX with Field Service Action and recall information regarding safety, compliance and emissions programs announced since 2000 for a specific vehicle. For complete information regarding programs or concerns about this vehicle, please contact a local Ford or Lincoln Mercury Dealer.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform vehicle owners of a safety defect or failure to meet minimum federal safety or emissions standards. Manufacturer recalls are repaired at no cost to the customer.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us: [facebook.com/CARFAX](https://www.facebook.com/CARFAX) [@CARFAXinc](https://twitter.com/CARFAXinc) [About CARFAX](#)

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

SYSTEMATIC RETRIEVAL OF THE CONTENT OR OTHER DATA FROM THIS SITE TO CREATE OR COMPILE, DIRECTLY OR INDIRECTLY, IN WHOLE OR IN PART, A COLLECTION, COMPILATION, DATABASE OR DIRECTORY WITHOUT THE EXPRESS WRITTEN PERMISSION OF CARFAX IS STRICTLY PROHIBITED. BY USING THE CARFAX VEHICLE HISTORY REPORT YOU AGREE TO THE CARFAX TERMS OF USE AND PRIVACY STATEMENT.

© 2026 CARFAX, Inc., part of S&P Global. All rights reserved.
6/7/26 10:56:19 AM (CDT)

CARFAX Warranty Check™

CARFAX has estimated the remaining original manufacturer warranty coverage based on information reported to us on this **2021 FORD BRONCO FIRST EDITION ADVANCED (1FMEE5EP1MLA40176)**.

Please confirm remaining factory warranty and extended warranty options with your dealer or vehicle manufacturer.

2021 FORD BRONCO FIRST EDITION ADVANCED	
VIN:	1FMEE5EP1MLA40176
Estimated start date of warranty:	07/09/2021
Last CARFAX reading reported on 11/28/2021:	236 miles
Today's date:	06/07/2026

Type of Coverage	Original Warranty	Estimated Remaining Coverage
Basic	36 months or 36,000 miles	Coverage Expired
Drivetrain	60 months or 60,000 miles	2 months or 59,764 miles
Emissions	No data reported to CARFAX	
Corrosion	60 months or unlimited mileage	2 months or unlimited mileage
Transferable	No data reported to CARFAX	
Roadside	60 months or 60,000 miles	2 months or 59,764 miles
Safety belt & inflatable restraint	60 months or 60,000 miles	2 months or 59,764 miles
Specific Components	No data reported to CARFAX	

i CARFAX Warranty Check provides an **estimate** of this vehicle's remaining warranty coverage. It does not take into account some vehicle history events such as some title brands that may void the original manufacturer warranty or ownership transfers that may decrease warranty coverage. This warranty information is only valid for vehicles manufactured for the United States. Complete warranty coverage information is available for this vehicle at the FORD website.

© 2026 CARFAX, Inc., part of S&P Global. All rights reserved.
6/7/26 10:56:19 AM (CDT)



CARFAX Buyback Guarantee

CARFAX Buyback Coverage:

06/07/2026 - 06/07/2027

CARFAX Vehicle Description:

2021 FORD BRONCO FIRST EDITION ADVANCED

VIN:
1FMEE5EP1MLA40176

Body Style:
4 Door Wagon/Sport Utility

Driveline:
All wheel drive

Engine:
2.7L V6 F DOHC 24V

You may qualify

if you find that any of these problems were reported by a U.S. Department of Motor Vehicles and were not included in this report.



Severe Damage:

Salvage/Junk
Rebuilt/Reconstructed
Dismantled
Fire/Flood/Hail



Odometer Problems:

Exceeds Mechanical Limits
Not Actual Mileage



Lemon History:

Manufacturer Buyback

Terms and Conditions Apply

[View Terms and Conditions for CARFAX Buyback Guarantee coverage](#)